



What can we do with your air ?

ARS+Full

30%

→ 30% recycled into HP air



20%

→ 20% recycled into LP air




Air consumptions efficiencies


Machines with both HP & LP entry lines:

Sidel serie 2, Kronos ...

No air recovery unit



ARS+Full



Depending on your machines, production and air network, switching OFF an HP compressor with ARS+ or a LP compressor with ARS can be considered, with significant savings on the compressor's maintenance